

4634 S. Presa Street San Antonio TX 78223-1000 210-533-1231 Phone ● 210-533-2211 Fax

PRODUCT BULLETIN: 11-004

SUBJECT: New Driver Required for Schlage Modular Cylinders

DATE: May 17, 2011

Note: Schlage has changed the cams on their 2010 model mortise "Modular" cylinders. If replacing cylinders on Southern Steel 10500 or 10600 locks with a new Schlage mortise "Modular" cylinder, a new driver is required and available:

Part Number 76767590 - List Price \$21.60

For technical assistance, please contact Joe Bucha, Technical Services, 210-531-4126.

SOUTHERN FOLGER DETENTION EQUIPMENT COMPANY
Kathee Forrest
Product Manager
210-531-2701
kforrest@southernfolger.com



